



August 27, 2012

Jeff Morris
 Division Chief
 Euless Fire Department
 Email: jmorris@ci.euless.tx.us

Quote # 7990A

Chief Morris,

Per your request we are quoting remounting and refurbishing your Frazer Type I 12' Generator Powered Module E-1590 onto a 2013 Ford F-350 6.7L diesel chassis with an air suspension system. For your convenience all pricing has been itemized below.

2013 Ford F-350 6.7L diesel chassis (order chassis Ford red)	\$ 36,750.00
Granning air suspension system (wire to dump w/o ignition ON)	\$ 6,000.00
Heat shielding for diesel chassis	\$ 1,500.00
*Remount of module (see below)	\$ 11,850.00
Optional items (listed below)	\$ 29,300.00
HGAC fee	\$ 600.00
Total	\$ 86,000.00

Remount of module includes:

- a) New black grille guard with (4) Whelen M4 series grille & intersect LEDs and (2) Federal Signal AS124 speakers
- b) New console and reuse Whelen 295SLSA1 siren
- c) Inspect all generator cabling, replace as needed
- d) New boot plate and boot
- e) New mounting rubber
- f) Rewire tail lights
- g) New under hood breakers
- h) Electrical check-out
- i) Add insulation to side and rear entry doors
- j) Replace entry door windows with double pane windows
- k) New weatherstripping and rivets for compartment and entry doors
- l) Replace all non-skid material on threshold(s)

Items included in above total:

Ship leaf springs from new chassis loose	\$ N/C
No striping or lettering on module or chassis	\$ N/C
New Onan 5.5kW generator w/ new fuel tank, fuel pump, non-permeable hoses and emissions canister kit (ship old genset loose)	\$ 5,200.00
(4) Whelen M7 series split red/clear grille & intersect LEDs in lieu of M4 series red (C/R-C/R-R/C-R/C)	\$ 450.00
Stainless steel wheel covers	\$ 350.00

Furnish and install (2) Federal Signal AS124 speakers	\$	incl.
Remove and reinstall speaker for EQ2B on grille guard and remove and reinstall control head for EQ2B in 4 th slot of console	\$	225.00
Remove and reinstall Whelen siren in 1 st slot of console	\$	N/C
Install your black nerf bars on chassis	\$	75.00
Remove existing exhaust tip from old chassis and ship loose	\$	N/C
Replace license plate light	\$	50.00
Replace stainless steel threshold on rear storage compartment insert	\$	75.00
Furnish and install gas shock on front I/O and O2 compartment doors	\$	100.00
Replace long lower storage compartment cables w/ gas shock	\$	100.00
Replace side entry door hold-open spring w/ gas shock & new head knocker	\$	250.00
Wire existing Opticom to new console w/ ON/OFF switch	\$	N/C
Console layout (Whelen siren-double switch panel-EQ2B head-(2) portable radio chargers – single thicker plate for Knox box)	\$	N/C
Remove and reinstall self-contained radio off front of console and speaker on floor in front of console facing ceiling (ignition hot)	\$	300.00
Remove and reinstall (2) portable radio charges in 5 th position of console (battery hot)	\$	225.00
Remove and reinstall Knox box on console (battery hot)	\$	200.00
Remove and reinstall laptop mount on passenger's side of console towards front w/ docking station	\$	150.00
Furnish and install new Gamber vehicle specific base for laptop mounting pole	\$	200.00
Remove and reinstall power supply inside console for docking station (battery hot)	\$	75.00
New 1 high glove box holder on back wall of truck cab mounted as high as possible	\$	100.00
Furnish and install (2) large map holders on rear wall of console	\$	150.00
Add blue knocker to end of squad bench	\$	N/C
Replace all cabinet doors w/ polycarbonate scratch resistant doors	\$	600.00
Repaint cabinets in module (reinstall equipment in front I/O cabinet and to bottom of action wall cabinet after paint)	\$	800.00
Install new stainless pieces lip up on shelf in I/O	\$	50.00
Install stainless piece on lip on shelf in driver's side front corner area	\$	50.00
Staple magnets to seat and back cushions	\$	N/C
Replace interior fluorescent ceiling lights with (8) Grote LEDs (ship old fixture and bulbs loose)	\$	3,000.00
Replace floor with new Alucabond subfloor and new Lonseal vinyl floor, replace existing O2 box w/ new style aluminum O2 box, replace thresholds w/ non-skid tape on top, install new cot plates and hook for Stryker Power-PRO	\$	3,400.00
175-3 single position cot mount	\$	incl.
Remove and reinstall antler and bar	\$	N/C
Strip, prime, and repaint module Ford red & Ford white (roof only of module is white, top trim is red)	\$	6,000.00
Make sure red paint on inside of on the unit near the door rubber is repainted	\$	N/C
4 high glove box holder in module above squad bench	\$	175.00
Replace air conditioner w/ new Dometic self contained A/C unit and modify interior wall panel and exterior to accommodate, mount thermostat at action wall (ship old A/C loose)	\$	5,000.00
Replace knockers above rear entry door and above CPR seat if there is notches left in them after the A/C is replaced	\$	N/C
Add full height corner knocker to corner of A/C wall	\$	75.00
Reinstall mounting hardware for acrylic holders on wall aft of CPR seat	\$	N/C
Remove Sigtronics jack and push-to-talk at actin wall and ship loose	\$	N/C
Remove black bracket at action wall for cell phone holder but leave cable there	\$	N/C
Remove papers on wall above squad bench and ship loose, clean tape markings on wall	\$	N/C
Remove Charge Wizard from battery charger	\$	N/C
Replace striker on rear back board compartment	\$	N/C
Replace rear entry door grabbers	\$	N/C
Remove fuel line cover from rear storage compartment	\$	N/C

Add arm rests on console	\$	200.00
Furnish and install Engel 15 qt. refrigerator w/ 120VAC adapter and locking hasp on stationary portion of laydown O2 box	\$	900.00
Furnish and install new stainless threshold at side entry door	\$	50.00
Install your new 30 amp auto eject on front wall of module, add new cabling for 30 amp outlet, add access panel in O2 compartment and add plate over existing shore power outlet holes	\$	650.00
Replace screwed on trim on inside on unit near rear entry doors	\$	75.00
Make sure all walls inside unit are wiped down	\$	incl.
Do not load loose items inside unit until customer has inspected completed unit	\$	N/C

*Remount fee includes credit for reusing Whelen siren

Per TMVCC we are quoting this through our licensed franchise dealer, Sterling McCall Ford.

All pricing is F.O.B. Houston.

Thank you for the opportunity to quote this job. If you have any questions please call me at 888-372-9371.

Best Regards,



Laura Richardson
Frazer, Ltd.

LGR:LV