



September 29, 2014

Jeff Morris
 Assistant Fire Chief
 Eules Fire Department
 Email: jmorris@ci.eules.tx.us

Quote #9333B

Chief Morris,

Per your request we are quoting remounting & refurbishing your Frazer Type I 12' Generator Powered Module, X-454 (E-1120), onto a 2015 Ford F-350 6.7L diesel chassis. For your convenience all pricing has been itemized below.

2015 Ford F-350 6.7L diesel chassis (order Ford red)	\$ 38,700.00
Heat shielding for diesel chassis	\$ 1,500.00
Granning air suspension (wired to dump w/o ignition ON)	\$ 6,700.00
Remount of Module (see Incl. items below)	\$ 15,000.00
Chassis Exterior Upgrades	\$ 1,225.00
Chassis Interior Upgrades	\$ 1,550.00
Module Exterior Upgrades	\$ 22,025.00
Module Interior Upgrades	\$ 10,950.00
Credit for reusing existing grille speakers in lieu of furnishing Federal Signal AS124	\$ -150.00
HGAC Fee	\$ 600.00
Total	\$ 98,100.00

Chassis Exterior Upgrades

1. Items included in remount fee:
 - a) Ranch Hand powder coated grille guard \$ Incl.
 - b) Frazer aluminum rear window pass through plate \$ Incl.
 - c) (2) Mega fuses with new wiring, relocated to engine bay \$ Incl.
 - d) Mounting rubber \$ Incl.
 - e) Make old chassis road ready, if applicable \$ Incl.
2. No striping or lettering on chassis \$ N/C
3. Furnish & install (2) Whelen M7 split red/clear grille lights w/clear lenses in lieu of furnishing (2) Whelen M4 lights
Layout: Clear/Red – Red/Clear \$ 225.00
4. Furnish & install (2) Whelen M7 split red/clear intersects lights w/clear lenses in lieu of furnishing (2) Whelen M4 lights
Layout: Clear/Red – Red/Clear
Note – Intersects will be installed in line with center cross beam of grille guard \$ 225.00

Quote #9333B

5. Furnish & install stainless steel wheel covers	\$	450.00
6. Remove & reinstall (1) BP200-EF speaker centered in the grille guard between your Whelen speakers	\$	225.00
7. Install your black nerf bars on chassis	\$	100.00
	Total \$	1,225.00

Chassis Interior Upgrades

8. Items included in remount fee:		
a) Furnish & install powder coated aluminum six position console	\$	Incl.
Note – Certain charges apply for labor required to remove & reinstall		
9. Front of Console – Remove & reinstall self contained radio w/existing coax, with speaker on floor		
Note – Wire large wire Battery hot & 2 nd smaller wire ignition hot	\$	300.00
10. Slot 1 – Furnish & install Whelen 295SLSA1 siren (ship old loose)	\$	Incl.
11. Slot 2/3 – Furnish & install (1) new double switch panel with new switches <i>Layout: Primary, Secondary, Blank, Opticom, Blank, Blank, Blank</i> <i>Interior Lights, Rear Load, Side Scene, Side Scene, Start/Stop</i>	\$	Incl.
12. Slot 4 – Remove & reinstall EQ2B control head	\$	300.00
13. Slot 5 – Remove & relocate (2) portable radio chargers to a modified plate Note – Plate should appear as X-910	\$	225.00
14. Slot 6 – Remove & reinstall Knox key secure mounted to single plate, wire ignition hot Note – Remove Knox face plate prior to delivery	\$	200.00
15. Rear of Console – Remove & reinstall dual map holder Note – Modify triple map holder to dual to accommodate chassis	\$	25.00
16. Furnish and install (1) large glove box holder on rear wall of chassis cab	\$	175.00
17. Remove & reinstall LIND power supply inside console Note – Wire Battery Hot and push power cord through front of console	\$	125.00
18. Furnish & install arm rests on console	\$	200.00
	Total \$	1,550.00

Module Exterior Upgrades

19. Items included in remount fee:		
a) Install ignition & fail safe solenoids on electrical shelf	\$	Incl.
b) Full electrical check	\$	Incl.
c) Generator system check & inspect all generator cabling, replace as needed	\$	Incl.
d) Rewire tail lights	\$	Incl.
e) New passthrough rubber boot	\$	Incl.
f) New ribbed rubber in compartments, if applicable	\$	Incl.
g) Replace all door compartment bumpers	\$	Incl.
h) Replace weather stripping on compartment and entry doors	\$	Incl.
i) Time save exterior compartment panels	\$	Incl.
j) Add new insulation to side & rear entry doors, if applicable	\$	Incl.
k) Replace entry door windows with double pane windows, if applicable	\$	Incl.
l) Side entry door-open spring, if applicable	\$	Incl.
m) Route exhaust to passenger side rear bumper cap, ship old exhaust tip loose	\$	Incl.

20. No striping or lettering on module	\$	N/C
21. Removal of rear conspicuity prior to paint		
Note – When repainting a module it is necessary to remove exterior conspicuity, failure to do so will result in bleeding of new paint under existing conspicuity	\$	650.00
22. Furnish & install 3M diamond grade fluorescent lime yellow conspicuity with translucent red overlay on entire rear wall including entry doors	\$	1,500.00
23. Furnish & install 2 magnetic style placards with holders (discuss numbering) Location: O2 compartment door centered below the latch and above the belt line stripe, front I/O centered above the belt line stripe and latch (discuss unit numbering)	\$	250.00
24. Stripe, prime and repaint A/C register, A/C vent, and A/C panel custom gray	\$	375.00
25. Stripe, prime, and repaint 12' Module Ford red (FA90:F1) including outer edge of outer roof trim	\$	6,500.00
Note – Items sub-listed (a-k) are included with paint unless stated otherwise		
a) Strip, prime, and repaint roof on module Ford white (FA:90:YO)	\$	Incl.
b) Furnish & install painted corner caps on module Note – Vertical edge will be painted Ford red (FA90:F1) & top edge will be painted Ford white (FA:90:YO)	\$	Incl.
c) Furnish & install new side entry door with new style powder coated panels	\$	Incl.
d) Furnish & install new rear entry doors with new style powder coated panels	\$	Incl.
e) Furnish & install stainless threshold on rear storage compartment	\$	Incl.
f) Replace compartment and entry door latches keyed J236	\$	Incl.
g) Replace marker lights	\$	Incl.
h) Remove & reinstall rear bumper	\$	Incl.
i) Remove & reinstall treadbrite panels	\$	Incl.
j) Remove and ship loose all listed emergency lighting below w/chrome flanges		
1. Remove (8) Whelen 900 series red box lights	\$	Incl.
2. Remove (5) Whelen 900 series front wall lights	\$	Incl.
3. Remove (3) Whelen 900 series rear wall lights	\$	Incl.
4. Remove (2) Whelen 508 clear load lights	\$	Incl.
5. Remove (2) Whelen 600 series rear BTT	\$	Incl.
k) Remove & reinstall (2) 300 watt Quartz halogen side scene lights Note – Wired to 2 switches on the console	\$	Incl.
26. Furnish & install new rear entry door grabbers (discard old)	\$	Incl.
27. Furnish & install cast LED license plate light (discard old)	\$	50.00
28. Clear lenses on listed emergency lights	\$	N/C
29. Furnish & install (8) Whelen M9 series red LEDs corner box lights w/converter flanges	\$	2,600.00
30. Furnish & install (5) Whelen M9 series LEDs on front wall w/converter flanges <i>Front Layout: Blue – Red – Clear – Red – Blue</i> Note – Use “random” flash pattern.	\$	1,625.00
31. Furnish & install (3) Whelen M9 series LEDs on rear wall w/converter flanges <i>Rear layout: Amber – Amber – Amber</i>	\$	975.00
32. Furnish & install (2) Whelen M9 series LEDs BTT w/chrome converter flanges	\$	600.00
33. Furnish & install (2) Whelen M9 series load lights w/converter flanges on rear of module, wired to come ON with rear entry door, furnish switch	\$	800.00
34. Add catch cable to long lower compartment positioned on left side	\$	100.00

35. Replace gas shock on front I/O compartment door (discard old)	\$	50.00
36. Replace gas shock on O2 compartment door (discard old)	\$	50.00
37. Replace gas shock on rear storage compartment door (discard old)	\$	50.00
38. Remove and reinstall existing Opticom and terminate to new chassis, wired OFF w/driver side door park kill and on/off switch at console	\$	Incl.
39. Install customer provided 30A auto eject on front wall of module, add new cabling for 30A outlet, add access panel in O2 compartment and add plate over existing shore power outlet holes (ship old loose)	\$	650.00
40. Furnish & install new Onan 5.5kW generator with non permeable hoses, emissions canister kit and add new 15 gal fuel tank and fuel pump, reuse existing exterior door ⁶		
Note – Please remove Onan generator prior to delivery of remount to Frazer.	\$	5,200.00
	Total \$	22,025.00

Module Interior Upgrades

41. Items included in remount fee:		
a) Reattachment of loose seat cushions	\$	Incl.
b) Replace all non-skid material on threshold(s) with black 3M non-skid material	\$	Incl.
c) Complete detail, if applicable		
1. Clean & wipe down lasco walls	\$	Incl.
2. Clean & wipe down floor of module	\$	Incl.
3. Clean & wipe down exterior & interior of cabinets	\$	Incl.
4. Clean & wipe down compartments and shelves	\$	Incl.
42. Furnish & install Onan buzzer kill switch at rear entry door with added plating	\$	250.00
43. Furnish & install rear load light switch at rear entry door	\$	125.00
44. Furnish & install magnets on all seat and back cushions (discard old)		
Note – Remove velcro, if applicable	\$	900.00
45. Furnish & install new Lexan scratch resistant doors on all module cabinets (discard old)	\$	775.00
46. Replace corner area counter top, front corner area wall and lower driver side wall all with stainless steel (discard old)	\$	750.00
47. Replace squad bench with stainless steel wrapper w/new opening and frame for trash can (discard old)	\$	650.00
48. Furnish & install dual glove box holder on wall above squad bench	\$	125.00
49. Furnish & install Engel 14qt. refrigerator with 120 VDC adapter and locking clasp ID 1864, on stationary portion of laydown O2 box	\$	950.00
50. Replace (8) fluorescent ceiling lights with (8) Grote LEDs (ship old loose)	\$	3,000.00
51. Replace floor with new Alucabond subfloor and new Lonseal vinyl floor, reuse existing O2 box, replace thresholds, install black non-skid tap on top, install new cot plates and hook for Stryker Power-PRO (discard old flooring)	\$	3,000.00
52. Furnish & install 175-3 single position cot mount	\$	Incl.
53. Remove & reinstall antler and bar	\$	N/C
54. Furnish & install Cobalt wise corner trim	\$	300.00
55. Relocate A/C thermostat to action wall, fill holes with screws if necessary	\$	125.00
	Total \$	10,950.00

Terms and Conditions

1. Quote valid for 90 days.
2. All pricing is F.O.B. Houston.
3. Per TMVCC we are quoting this through our licensed franchise dealer, Sterling McCall Ford.
4. Please make your purchase order out to Sterling McCall Ford, 6445 Southwest Freeway Houston, TX 77074. Please email a copy of your purchase order and this quote to Pablo Cantu with Sterling McCall Ford at pcantu@sterlingmccallford.com and to Adam Fischer at sales@frazerbilt.com.
5. Payment for the entire purchase is due upon receipt and acceptance of completed unit.
6. Please remove the Onan generator prior to delivery at Frazer for remount.

Thank you for the opportunity to quote this job. If you have any questions please call me at 888-372-9371.

Best Regards,



Laura Richardson
Frazer, Ltd.

LGR:AD